

Infrared inspection of ceiling insulation identifies missing insulation



Above, inspection above ceiling tiles shows insulation (yellow) is patch instead of forming a continuous layer. The red areas on the infrared scan below indicate areas of high heat gain – where insulation is missing. Ceiling temperature at the cross hairs is 85.3 degrees – about 10 degrees higher than the desired room temperature.

